



## TO TAKE OFF W/O RADIUS




### Description

Take-off without radius.

### Ordering example

Product TO 200  
 Dimension  $\varnothing d_1$

### Dimensions



$\varnothing d_1$ nom	m kg
<b>63</b>	<b>0,06</b>
<b>80</b>	<b>0,08</b>
<b>100</b>	<b>0,07</b>
112	0,10
<b>125</b>	<b>0,11</b>
140	0,15
150	0,15
<b>160</b>	<b>0,16</b>
180	0,19
<b>200</b>	<b>0,21</b>
224	0,36
<b>250</b>	<b>0,36</b>
280	0,30
300	0,36
<b>315</b>	<b>0,54</b>
355	0,41
<b>400</b>	<b>0,58</b>
450	0,71
<b>500</b>	<b>0,83</b>
560	0,96
600	0,99
<b>630</b>	<b>1,13</b>
710	1,58
<b>800</b>	<b>2,11</b>
900	2,70
<b>1000</b>	<b>3,23</b>
1120	4,10
<b>1250</b>	<b>4,55</b>